## National Transportation Safety Board NTSB ID: DEN03LA010 Aircraft Registration Number: N219DF FACTUAL REPORT Occurrence Date: 10/19/2002 Most Critical Injury: None Occurrence Type: Accident Investigated By: NTSB ETYBO Location/Time Nearest City/Place State Zip Code Local Time Time Zone CO 80137 1241 MDT Watkins Distance From Landing Facility: Direction From Airport: Airport Proximity: On Airport Aircraft Information Summary Aircraft Manufacturer Model/Series Type of Aircraft Hildebrandt Rutan/Defiant Airplane Sightseeing Flight: No Air Medical Transport Flight: No

## Narrative

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

On October 19, 2002, at 1241 mountain daylight time, a Hildebrandt Rutan/Defiant, N219DF, was substantially damaged during a forced landing following a loss of engine oil pressure at Front Range Airport, Watkins, Colorado. The private pilot, the sole occupant aboard, was not injured. Visual meteorological conditions prevailed, and no flight plan had been filed for the personal flight being conducted under Title 14 CFR Part 91. The local flight originated at 1240.

The following is based on the pilot's accident report. After taking off on runway 26 and turning onto the crosswind leg, the pilot noticed the rear engine oil pressure was dropping. After turning onto the downwind leg, the pilot reduced power on the rear engine to idle. When he was on final approach and felt assured of landing on runway 26, he shut down the rear engine. When he retarded the throttle on the front engine, he noticed power was not decreasing. He secured the front engine by turning off the ignition and glided to a landing but he forgot to lower the nose landing gear. The airplane touched down, the nose struck the runway, and the airplane skidded to a halt on the runway. The airplane's nose section, including the "Rhino" rudder, was crushed and several fuselage bulkheads were buckled.

Examination of the airplane disclosed the front engine throttle cable had broken, and there was a broken oil pressure sensor line in the rear engine. In his accident report, the pilot noted that the accident could have been prevented if he had followed "better emergency procedures --- use of the emergency checklist."

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: DEN03LA010

Occurrence Date: 10/19/2002

				10/10/2002								
AVIATION		Occurrence Type: Accident										
Landing Facility/Approach Info	ormation											
Airport Name		A	Airport ID:	Airport Eleva	ort Elevation Runway Used		way Used	Runway Length		h F	Runway \	Width
Front Range		I	FTG	5512 Ft.	MSL	26 800			000 10		100	
Runway Surface Type: Asphalt												
Runway Surface Condition: Dry												
Type Instrument Approach: NONE												
VFR Approach/Landing: Forced Landing												
Aircraft Information												
Aircraft Manufacturer Hildebrandt				/Series n/Defiant					Serial 039	l Number		
Airworthiness Certificate(s): Experimental (Special)												
Landing Gear Type: Retractable - Tricycle												
Homebuilt Aircraft? Yes	Certified Max Gross Wt.				3400 LBS Number			er of Engines: 2				
Engine Type: Reciprocating						Model/Series: Rated						
- Aircraft Inspection Information							-					
Type of Last Inspection			Date of Last Inspection Time S			ime Sir	nce Last Insp	ection	Airframe Total Time			
Annual			10/2002				3 Hours				605	Hours
- Emergency Locator Transmitter (E	LT) Information											
ELT Installed? Yes	ELT Operate	ed? No	ELT Aided in Locating Accident Site?									
Owner/Operator Information												
Registered Aircraft Owner			Street Address On File									
Gregory A. Benson			City							State CO	Zip 802	Code
Operator of Aircraft			Street Address									
Operator of Aircraft  Same as Reg'd Aircraft Owner			Same as Reg'd Aircraft Owner City							State	Zip	Code
Operator Does Business As:						Op	erator Desig	nator Co	ode:			
- Type of U.S. Certificate(s) Held: N	one											
Air Carrier Operating Certificate(s):												
Operating Certificate: Operator Certificate:												
Regulation Flight Conducted Under:	Part 91: Genera	Aviation	on									
Type of Flight Operation Conducted:	Personal											
FACTUAL REPORT - AVIATION Page 2											age 2	

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: DEN03LA010

Occurrence Date: 10/19/2002

	AVIATI	QN	Occurrence Type: Accident					1							
First Pilot	Information								•						
Name						City				St	ate	Date of Birth	Age		
On File						On File	le On Fi					On File	37		
Sex: M	Seat Occupied:	: Left	Pri	ncipal Profes	sion: Unkno	wn	Certificate Number: On File								
Certificate(	s): Priva														
Airplane Rating(s): Multi-engine Land; Single-engine Land															
Rotorcraft/Glider/LTA: None															
Instrument Rating(s): None															
Instructor Rating(s): None															
Type Rating	g/Endorsement fo		С	urrent Bie	nnial Flig	ht Revie	ew? 04/								
Medical Ce	rt.: Class 3	Medica	al Cert. Statu	s: Valid Me	dicalno wa	aivers/lir	n.		Date o	of Last N	/ledical l	Exam: 05/200	1		
- Flight Time Matrix  All A/C  This Make and Model		Airplane Single Engine	Airplane Mult-Engine	Night		In Actual	Instrument ual Simulate		Rotorcraft	Glider	Lighter Than Air				
Total Time		575	22	553	22		60			7					
Pilot In Con	nmand(PIC)	486	22	486	22		60			7					
Instructor															
Last 90 Day	/S	2	2		2										
Last 30 Day		2	2		2				_						
Last 24 Hou						<u> </u>							_		
Seatbelt Us	sed? Yes	Shou	ılder Harness	Used? Yes		Т	oxico	logy Perf	ormed? N	lo		Second Pilot?	No		
Flight Pla	n/Itinerary														
	ht Plan Filed: No	one													
Departure F						;	State	A	Airport Identifie		Depa	arture Time	Time Zone		
Watkins	_						co	F	FTG		1240		MDT		
Destination							State Airp		Airport Identifier						
Local Flig	ht							F							
Type of Cle	arance: None					-		-							
Type of Airs	space: Class	E													
Weather	Information														
Source of I	Briefing: Unkno	wn													
Method of	Briefing: Unkno	wn													
				FACTUAL	REPORT	- AVIA	TION	1					Page 3		

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: DEN03LA010

Occurrence Date: 10/19/2002

Occurrence Type: Accident

	ETYBOR		Occurrenc	Occurrence Type: Accident										
Weather Information														
WOF ID	Observation Time	Time Zone	WOF Elevati	on	WOF Di	istance Fro	m Accid	dent Site		Direction From	n Accident Site	<del>-</del>		
FTG	1243	MDT	5512 Ft.	. MSL				NM			Deg.	Mag.		
Sky/Lowes	st Cloud Condition: Clear	ſ				Ft. AGL			Condition of Light: Day					
Lowest Ce	illing: None		Ft.	AGL	Visibi	ility:	10	SM	Alti	meter:	30.06	"Hg		
Temperatu	ure: 12 °C [	Dew Point:	-5 °C	-5 °C Wind Direction: 50 Density Altitude:								Ft.		
Wind Spee	ed: 3	Gusts:		Weather Condtions at Accident Site: Visual Conditions										
Visibility (R	RVR): Ft.	Visibility (RV	/V)	SM	Intensity	y of Precipi	tation:							
Restriction	Restrictions to Visibility: None													
Type of Precipitation: None														
Accident	Information													
Aircraft Dar	mage: Substantial		Aircraft Fire	rcraft Fire: None					Aircraft Explosion None					
Classificati	on: U.S. Registered/U.	.S. Soil												
- Injury Sur	mmary Matrix	Fatal Seri	rious Mino	or	None	TOTAL								
First Pil	lot				1	1	ī l							
Second	d Pilot						7							
Studen	at Pilot						1							
Flight In	nstructor						1							
Check I	Pilot						1							
Flight E	Engineer						7							
Cabin A	Attendants						7							
Other C	Crew						7							
Passen	ngers						7							
- TOTAL A	ABOARD -				1	1	1							
Other G	Ground						1							
- GRAND	O TOTAL -				1	1	ı]							

National Transportation Safety Board

FACTUAL REPORT AVIATION NTSB ID: DEN03LA010

Occurrence Date: 10/19/2002

Occurrence Type: Accident

А	ď	m	in	ist	rat	ίv	e l	Ini	fο	rr	ทล	ati	O	n
,	·			v	.ı uı		•		$\cdot$		110	ΛLI		

Investigator-In-Charge (IIC)

Arnold W. Scott

Additional Persons Participating in This Accident/Incident Investigation:

Robert C Bunderson Aviation Safety Inspector - Airworthiness FAA Flight Standards District Office 26805 E. 68th Avenue, Suite 200 Denver, CO 80249